

Conrail Cyclopedia

EMD SD40: Renumbering Locomotive Roster

<http://crcyc.railfan.net/>

Updated: 9-2-16



During the early 1990s, Conrail began receiving new C40-8W's, placing them in the 6200 series. Since some SD40's that had not been rebuilt or sold off still remained on roster, they were temporarily renumbered.

SD40's that had been stored inoperable at the time, even though many were later reactivated, were renumbered into the 600 series, placed into Conrail's leasing arm, repainted solid blue with CRL markings. These units apparently remained on Conrail property until late 1994, and then they were shipped to Helm Leasing. To make matters confusing, Helm painted out the 'L' from the 'CRL' markings on the cab sides and leased them back to Conrail, where they continued operating during the 1990's.

Those SD40's that were active or operable, on the other hand, were renumbered into the CR 800 series and never placed into the leasing arm. Several units in the 800 series were prefixed with "0" to either avoid confusion with Amtrak's 800-series F40's or to comply with Conrail's computer system, which was accustomed to 4-digit road numbers. Number 807 never had a locomotive assigned to it, therefore a CR 807 locomotive does not appear on the roster.

Unit #	Former	Prior	Previous	Built #	Retired	Fist Disposition
CRL 600	CR 6344	PC 6091	PRR 6191	03/66 31346	07/93	to HLCX 5015
CRL 601	CR 6293	PC 6040	PRR 6040	02/66 31285	07/93	to HLCX 5016
CRL 602	CR 6277	PC 6277	--- ----	12/71 37003	07/93	to HLCX 5017
CRL 603	CR 6280	PC 6280	--- ----	12/71 37006	07/93	to HLCX 5018
CRL 604	CR 6347	PC 6094	PRR 6194	03/66 31349	02/94	to HLCX 5019
CRL 605	CR 6310	PC 6057	PRR 6057	02/66 31302	02/94	to HLCX 5020
CRL 606	CR 6321	PC 6068	PRR 6068	02/66 31313	05/94	to HLCX 6214
CRL 607	CR 6251	PC 6251	--- ----	12/70 36907	07/93	to HLCX 5021
CRL 608	CR 6258	PC 6258	--- ----	12/70 36914	02/94	to HLCX 5022
CRL 609	CR 6262	PC 6262	--- ----	12/70 36918	07/93	to HLCX 5023
CRL 610	CR 6274	PC 6274	--- ----	12/71 37000	07/93	to HLCX 5024
CRL 611	CR 6312	PC 6344	PRR 6059	02/66 31304	07/93	to HLCX 5025
CR 0800	CR 6241	PC 6241	--- ----	12/70 36897	08/94	to EMD 6406
CR 801	CR 6242	PC 6242	--- ----	12/70 36898	01/96	to HLCX 5035
CR 0802	CR 6243	PC 6243	--- ----	12/70 36899	10/95	to IHB 4001
CR 803	CR 6246	PC 6246	--- ----	12/70 36902	10/95	to ?
CR 0804	CR 6247	PC 6247	--- ----	12/70 36903	10/94	to EMD 6431
CR 805	CR 6248	PC 6248	--- ----	12/70 36904	01/96	to HLCX 5026
CR 0806	CR 6249	PC 6249	--- ----	12/70 36905	10/94	to EMD 6432
CR 0808	CR 6255	PC 6255	--- ----	12/70 36911	01/96	to ?
CR 0809	CR 6256	PC 6256	--- ----	12/70 36912	01/96	to HLCX 5027
CR 810	CR 6257	PC 6257	--- ----	12/70 36913	01/96	to HLCX 5028
CR 0811	CR 6260	PC 6260	--- ----	12/70 36916	10/95	to HLCX 5029
CR 0812	CR 6261	PC 6261	--- ----	12/70 36917	01/96	to HLCX 5030
CR 0813	CR 6263	PC 6263	--- ----	01/71 36919	08/94	to EMD 6411
CR 0814	CR 6264	PC 6264	--- ----	01/71 36920	10/95	to HLCX 5031